

INSPECTION REPORT

Inspector's Name Morris, Craig R		Inspector's Signature CRAIG MORRIS <small>Digitally signed by CRAIG MORRIS Date: 2022.05.06 11:19:18 -07'00'</small>				Inspector's ID No. 62749	Report No. 17	Date yy mm dd 2022 04 28					
Railroad/Company Name & Address VIRGINIA & TRUCKEE RR CO., INC. P.O. BOX 467 VIRGINIA CITY NV 89440					R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name THOMAS GRAY Title OWNER Email Signature _____						
From: City VIRGINIA CITY		Codes 0209	Destination City & County			Codes	From Latitude						
State NV		32	City				From Longitude						
County STOREY		C029	County				To Latitude						
Mile Post: From		To	Inspection Point ENGINEHOUSE				To Longitude						
Activity Code:	230												
Units:	2												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
I	VTRR	18	STM	230	0016	A1			SHOP	N	N	1	
Description No exception taken during observation of annual inspection of steam locomotive. Railroad employees entered the boiler through the steam dome and the interior was examined. The mud ring, crown sheet, front and rear tube sheets were viewed via borescope with no exceptions taken.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?				

INSPECTION REPORT

Inspector's Name Morris, Craig R		Inspector's Signature CRAIG MORRIS <small>Digitally signed by CRAIG MORRIS Date: 2022.05.06 11:18:41 -07'00'</small>			Inspector's ID No. 62749	Report No. 16	Date yy mm dd 2022 04 27						
Railroad/Company Name & Address VIRGINIA & TRUCKEE RR CO., INC. P.O. BOX 467 VIRGINIA CITY NV 89440				R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name THOMAS GRAY Title OWNER Email Signature							
From: City VIRGINIA CITY		Codes 0209	Destination City & County			Codes	From Latitude						
State NV		32	City				From Longitude						
County STOREY		C029	County				To Latitude						
Mile Post: From		To	Inspection Point ENGINEHOUSE				To Longitude						
Activity Code:	230	230T											
Units:	1	1											
Sub Units:	0	0											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	VTRR	18	STM	230	0036	A1			SHOP	N	N	1	
Description No exception taken during observation of satisfactory hydrostatic test of steam locomotive. MAWP is 180 psi and the hydrostatic test was performed at 225 psi with firebox metal temperature at 75 degrees fahrenheit. FRA observed railroad employees perform hammer tests of staybolts. The smokebox was inspected with no exceptions taken. The following water leaks were observed during test: Firebox - one fusible plug leaking, two fusible plugs seeping. Left injector leaking Turret valve leaking Whistle valve leaking Firebox door upper stud leaking Staybolt engineer's side bottom row forward of blow down has telltale hole seeping.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			